

TO BE FILLED BY THE INSPECTING OFFICER


- 1 Name of Officer : SHINE.P.R
2 Name Of School : Villa Nazareth English Mediam School ,Palaikonam.
3 Location with Edn. Dist/Sub.Dist : Palaikonam, Attingal/ Nedumangadu
4 Classification of Building and size (basis for :
i. Permanent (Single or multi storied) 1) 53.50 X 10.05 X 7.20 M + 2.00 X 36.10X6.65X7.20
+ 37.05X6.45X7.20M+2.85MM wide Verandah
(Double Storied R.C.C Roof Building)
ii. Semi permanent :
iii. Temporary :
5 Period for which the certificate issued : 2024 - 2025
6 Nature of defect, if any :
a. Foundation and basement :
b. Superstructure :
c. Doors and Windows :
d. Wood work wrought and put up : Nil
e. Roof :
f. Flooring :
g. Misc. (Cracks etc) :
7 Any major defects noticed which will render the : No
8 Whether maintenance work have been : Yes
9 Whether structure is sound or not for : *Structure is sound to conduct classes under normal*

Note

- 1 The stability of structure should be examined also with reference to location, altitude, intensity of wind
 - 2 Any additional observations if deemed necessary for the certificate may be furnished separately with
 - 3 All directions given as per Circular No W(1)39792/2017/DGE dtd 05.10.2021 should be compiled
- Certified that the school was inspected by me on 27.05.2024 and found fit to conduct classes or the*

Place: Aryanadu
Date: 28.05.2024

Signature
Designation



ASSISTANT ENGINEER
LID & EW SECTION
ARYANAD GRAMA PANCHAYAT